

## **Pre-Proposal Conference and Site Tours For the PPPO DUF6 RFP**

The US Department of Energy's (DOE) Environmental Management Consolidated Business Center, Cincinnati, Ohio issued the Final Request for Proposal (RFP) on June 17, 2009 for operation of two depleted uranium hexafluoride (DUF6) conversion facilities. These facilities will convert the DOE's inventory of DUF6 to a more stable chemical form for beneficial reuse or disposal. One conversion facility is located near Portsmouth, Ohio; the other conversion facility is located near Paducah, Kentucky.

### **NOTICE:**

This Pre-Proposal Conference is for informational purposes only. All attendees are cautioned that proposals must be based on the information provided in the final RFP and any amendments thereto. In the event of any discrepancies between the information provided during this Conference and the final RFP, the final RFP shall take precedence.

### **Pre-Proposal Conference**

DOE will be conducting a Pre-Proposal Conference on July 14, 2009 at the Western Kentucky Technical and Community College Crounse Hall Room 101 located at 4810 Alben Barkley Drive, Paducah, KY 42002-7380. Registration will be from 8:15 am to 8:50 am. The Pre-Proposal Conference will begin at 9:00 am and end at approximately 11:45am. Sign-In for both Site Tour times will be held during the Pre-Proposal Conference registration.

### **Paducah Site Tour**

A site tour of the Paducah DUF6 Conversion Facility will be conducted following the Pre-Proposal Conference, which will begin approximately at 1:00pm on July 14, 2009. Tour buses will depart from and return to the Western Kentucky Technical and Community College Crounse Hall and will transport participants to the DUF6 Conversion Facility.

### **Portsmouth Site Tour**

An additional site tour of the Portsmouth Conversion Facility will be held on July 16, 2009. Site tours will begin at approximately 9:00am. Attendees are to arrive 15 minutes prior to their assigned tour time at the Portsmouth Facility, 3930 US Highway 23, Building X-1100, Piketon OH, 45661. Maps of the Portsmouth DUF6 Facility will be made available at the Pre-Proposal Conference.

### **General Instructions**

Interested companies shall submit a list of attendee(s) via e-mail to [wilmari.delgado@emcbc.doe.gov](mailto:wilmari.delgado@emcbc.doe.gov) no later than 4:00 p.m. Eastern Time July 10, 2009. This list should indicate whether the attendees plan to attend the Pre-proposal Conference, the Paducah Conversion Facility Site Tour, the Portsmouth Conversion Facility Site Tour, or both site tours. Attendees planning to attend either of the site tours must also submit a completed Site Tour

Registration Sheet (attached) for each visitor. For logistical purposes, the number of attendees per company for the site tours is limited to two (2). In addition, please identify a single point of contact.

You must bring a State or Federal Government Issued photo ID to attend either of the tours (driver's license, military ID, Passport, Federal agency site ID, etc.). Only US citizens will be allowed to participate in the Site Tours.

If you register to go on the tour and cannot attend, please notify Wilmari Delgado at (513) 246-0566 or via e-mail at [wilmari.delgado@emcbc.doe.gov](mailto:wilmari.delgado@emcbc.doe.gov)

Questions from the Pre-Proposal Conference and site tours must be submitted, in writing, at the end of the each event. 3x5 cards will be available at the beginning of each event. Responses to questions submitted will be posted on the DUF6 web-site.

It is expected that portions of the tour(s) will require walking; therefore, please wear appropriate attire suitable for an industrial environment, and made of natural fibers (cotton or wool). Safety shoes are not required; however, shoes worn shall be closed-toed, made of leather or other substantive materials (not cloth). Heels shall not be greater than one inch when measured from the bottom of the sole to the bottom of the heel. Hard hats and safety glasses will be provided.

The following items are prohibited on the tour(s):

1. Firearms or dangerous weapons
2. Drugs
3. Alcohol
4. Photographic equipment
5. Cell phones
6. Laptops
7. PDAs/Blackberrys
8. Computer-associated equipment (USB flash drives, CDs, MP3s, etc.)

The DOE, Western Kentucky Technical and Community College or OSU Endeavor Center will not be responsible for securing any items during the tour so it is recommended they be locked in your vehicle. Please keep hand-carried items to a minimum.

## CONVERSION FACILITY SITE TOUR REGISTRATION SHEET

Visitor will attend: ☐ Portsmouth ☐ Paducah ☐ Both Tours

**PLEASE TYPE OR PRINT:**

Full Name: \_\_\_\_\_  
(As it appears on your photo identification)

Visitor's Title:  
\_\_\_\_\_

Company Name and Address:  
\_\_\_\_\_  
\_\_\_\_\_

Company Telephone Number:  
\_\_\_\_\_

FAX Number:  
\_\_\_\_\_

Social Security Number:  
\_\_\_\_\_

Date of Birth:  
\_\_\_\_\_

Citizenship: \_\_\_\_\_

Home Address:  
\_\_\_\_\_  
\_\_\_\_\_

Home Telephone Number:  
\_\_\_\_\_